\_ JOB NO. 4940 - > BARGE: EIT113

BASF 1/96

. . .

FOREI	MARINE SERVICE FREEPORT, TE MAN'S DAILY T 4940 1-9-96 ETTII	E CORP. XAS TIME REPORT	We a new more solver	370	Govern Charles	bleve programme bon	Crop out James	plate on # 2 wing	Lange Langer Lange	Fisher of Dunger week	And buddlerthert	1 Desmar	100 P	H 0 H
BADGE NO.	NAME	:												
53	CLAUDIO DU	ARTE	117	,		/3	     							
70	JUAN RIVER	A	112/											
60	JOE OLIVAR	EZ								-		}		
579	LUCIO NAJE	RA				18								
664	JOSE CASAS		1/1/											
49	GABRIEL DE	LAROSA				h /8		-						
343	JOSE G. GO	MEZ												
229	DANIEL HER	NANDEZ				3								
507	Í 4	VA '									_			<u></u>
683	. V 	ALEZ												<u> </u>
73	F 2	RIGUEZ										<u> </u>		
72	) 	:GUEZ												
08	SAM PETTIT					3/2								
	TOTAL	HOURS												53
GNED	25444	Ç.	ODED AND TENDED					!	APPROVE 34	<u></u>				

		01/A	indi.	/ J	<b>%</b> ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~				//
	DHTE: 1-9-96	70 30 4 01/4					<i>J</i>		
	EMPLOYEE			<u> </u>					HOOVES
,	GABRIEL DELA ROSA		8/1/2						i
	DANIEL HERNANDEZ		8/61						· 
	Lucio NAJERA		861						
	JOE OLIVAREZ			ĺ	X				
	SAM PETTIT	1/	2/	3	3				
	CLAUDIO DUARTE		) D						
	JOSE' CASAS								
	JUNN RIVERA					· <u></u>			3
	LUPE GOMEZ						,		7_
	IgNACIO SILVA								* ! !
,	VICTOR GONZALEZ								
	RICHARD RODRIGUEZ			ı					
_	TRINO BODRIGUET								
Job Disc <i>kie</i> t	IN + Time worker:	1 +4		1	4				ऽन
700 - 800 70m - 8AM		HERNI	ANDE	1.10	/a S	A M	· · ·	·	
	PREPARING EquiPM						<del></del>	·····	
800 = 930	STATIO BOY THE CHE		· _ = @ :	receir e	0 T.E	112			
930 - 120	STORT TO CROPAUT D	ENA	() CF ()	ATE	202 S	دطه کا	neck	0 F.#	7 / Jug 0 Ta
A4 -/ FM	START TO CROP OUT D	155	Δ <sub>H</sub> , n	FIT		1 8in	le a F	BAR	r e
130 = 4 pm	WELD INSIDE & G	aug.	= 3 (1)	=/0-0	UT S	dos	100	CLAN	z )
TEM -10 PM	PAINT NEWPLATE	- 1	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				<del> </del>		
San = 930	CHEMIST INSPECT	IA RO	sa R	EMO	vEV	ENT	LINE	s <i>Tal</i>	FAR _
1030=122 1230=430	M INSTALL VENT XIN 2 SAM PUMP WATER SAMCLAUDIO JUAN	IE ST KOF, TURN	FOF VERI	The Zaul	KAN V E	KS #	<u>\$</u> ₹27 (128	o pro	· E
4声前=5章	W OHM CLADO O JOHN					e transport († 1920) 1931 - Harris Marie († 1920) 1931 - Harris Marie († 1920)		HEF	00032

The first of the f

Louir 239-1001 DATE: 1-8-96 TOTIL EMPLOYEE GABRIEL DELAROSA DANIEL HERNANDEZ Lucio NAJERA JOS OLIVAREZ SAM PETTIT CLAUDIO DUARTE JOSE' CASAS JUAN RIVERA LUPE GOMEZ IgNACIO SILVA VICTOR GONZALEZ RICHARD RODRIGUEZ TRING BODRIQUEZ DUAYY 8:00AM: 10:00 PM AC. 701 9-30 Am: 6:30 PM Ett=113

HERCULES
MARINE SERVICES CORPORATION

P. O. Drawer O . Freeport, Texas 77541

INVOICE NO.

3291-96

DATE

January 18, 199

Job No.

4940-2

Location

Freeport

TO: BASE

602 Copper Road Freeport, TX 77541 PLEASE REMIT PAYMENTS TO: 11011 RICHMOND

SUITE 500

HOUSTON, TX. 77042

PO#F91392

Terms : Net 30

FOA:

Service to ETT113 as follows:

Crop out damaged plate on side and deck of #2 wing tank; lay out plate and angles and fit on side of barge; weld inside and gauge and weld outside; clean and paint new plate; remove vent line stack; assist chemist in inspection; install stack; blow pipeline for Bobby Fuller's ok.

Labor:

Leadman

Leadman

Journey Journey

Marine chemist

Materials: 4 x 8 x 3/8" plate, angle iron, welding rods, cutting rig

TOTAL AMOUNT DUE

\$3,040.25

**HER 00035** 

PHONE: (409) 233-6371



P. O. Drawer O . Freeport, Texas 77541

INVOICE NO.

3291-96

DATE

January 18, 199

Job No.

4940-2

Location

Freeport

TO:

BASF 602 Copper Road Freeport, TX 77541

PLEASE REMIT PAYMENTS TO: 11011 RICHMOND

SUITE 500

HOUSTON, TX. 77042

PO#F91392

Terms

: Net 30

FOR: Servi

Service to ETT113 as follows:

Crop out damaged plate on side and deck of #2 wing tank; lay out plate and angles and fit on side of barge; weld inside and gauge and weld outside; clean and paint new plate; remove vent line stack; assist chemist in inspection; install stack; blow pipeline for Bobby Fuller's ok.

Labor: Leadman

Leadman

Journey Journey

Marine chemist

Materials: 4 x 8 x 3/8" plate, angle iron, welding rods, cutting rig

TOTAL AMOUNT DUE

\$3,040.25

PHONE: (409) 233-6371

## \*\*\* TRANSMISSION REPORT \*\*\*

PRINT TIME 01/18 '96 11:27 ID:HERCULES OFF. FREEPORT .409-233-1568

No.	START TIME	MODE	LOCATION		STORE PAGE			TOTAL TIME	CODE
40	01/18 11:27	TX	2666728	•	ADF	1	0	00'35"	0K

mx \$3291-96 only

26.6128

## Job workscope/Breakdown

JOH NO:	CUSTOMER:	Bast		_barce:_ <i>&amp;</i>	++ 113	<del>-</del>
FOREMAN:						
LEADMAN:						
JOURNEY:						
DTSPOSAL:	. 1 - (	CAL 0 .35				
MATERIAL: Change	15T,	PLUS		• ———	00.00	
STOCK MATERIAL:	. C 48.8	PLU:		9 65	0.00	
RQUIP:	372 X	5 20 Augu IR Weldows Rod	• N .			
COMPRES	SOR	my key for the	0 44.00			
NIR MÓV			e 5.00			•
FORKINE		and Harman Area (	_e 20.00			
TUCHUAT		1. 建二烷基化			die	
STEAM R		· 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	_e 80.00		<u>~</u>	
VYCHUM	-	"全国"""""	00.05			
סוז מאגוו	- ap	Section Section Section 1	0 10.00	-		
	MACHINE (		_e 15.00		<del></del>	
CHERRYP		- glack Children	_e 50.00			
CRANE	-CALIN	and the control of	e 30.00 00.0019		<del></del>	
PLATBED		ev 1. Symptotic di	e 20.00			
3" CAS	-	a language de la company	e 20.00 _e 14.00		· ·	
		tuaricha exister .	_0 14.00 _0 12.00			
2" STRI		4-1-1	_			
BUTTERW		The Secretary of the Se	_0.10.00		a.	
	TRIC PUMP	36.2 1 1 1 1 1 1	_0 15.00	<del> </del>		
WORK BA		<b></b>	<u>.</u> 0.35.00	***************************************		
CUTTING		1 11 216 March	_0 a.oo			
HAUL OU	<b>T</b>	নাল নাম্বর নিয়ুক্তির বিষয়ে হয়। কর্	01100.00/	day .	<u> </u>	
						•
ARRIVED:	COMPI	ETED:	DF	EPARTED:		
PRODUCT:	IOM				المستعمر	
					3,040.2	5-
	TOT	AL INVOICE:			<u></u>	

John W. Sansing MARINE CHEMIST CERTIFICATE # 4940 1509 Kilgarlin In. Tel. 713-478-4091 SERIAL NO. F 68114 Deer Park, Tx. 77536 HENCULES MEXINE Three (3) Carooes NOTES: (1) \* PROVIDE FORCED VENTILATION IN CAGO THATS, PROVIDE FOCKED WEST /4TTON SAFE FOR IN-SHYPYMED SHIFTHE WESU 173: 45 C4460 THATES: ZO. 8% UNGEN; CEWYO D 250 PPM CYCLINES KD Wids: 20.890 UKyGEN; TERNES WEL OTO 5 PPH CYCLONEUME ( WC (C) KOW used STEEN - FIlled WITH HATER-Voids - FillEd WITH WATER - SAFE FOR HOT WHEN MOIL DIS WINGS SAFE FEE WEXXELS SAFE FOR HOT WORL TUNKS KSDITTOMS ENTRE WITH KEETKOTTON SAFE HOW HOT WOULD CANDO DED WE: VAYARE IPYPING; STKYPSING PUPIL Duys Ectia In the event of any physical or atmospheric changes adversely affecting the STANDARD SAFETY DESIGNATION of the above spaces, or if in any doubt, immediately stop all work and contact the undersigned Marine Chemist. QUALIFICATIONS: Transfer of ballast or manipulation of valves or closure equipment tending to after conditions in pipe lines, tanks or compartments subject to gas accumulation, unless specifically approved in this Certificate, requires inspection and endorsement or relssue of Certificate for the spaces se affected. All lines, vents, heating coils, valves, and similarly enclosed appurtonances shall be considered "not sale" unless otherwise specifically designated. STANDARD SAFETY DESIGNATIONS (partial list, paraphrased from NFPA 306 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2) SAFE FOR WORKERS: Means that in the compartment or space so designated: (a) the oxygen content of the atmosphere is at least 19.5 percent by volume; and that, (b) toxic materials in the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT SAFE FOR WORKERS: Means that in the compartment or space so designated, the requirements of Safe for Workers have not been met. ENTER WITH RESTRICTIONS: Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified SAFE FOR HOT WORK: Means that in the compartment so designated: (a) oxygen content of the almosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration of flammable materials in the atmosphere is below 10 percent of the lower flammable limit, and that, (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire, and while maintained as directed on the Marine Chemist's Certificate; and further, that, (d) all adjacent spaces containing or having contained flammable or combustible materials have been cleaned sufficiently to prevent the spread of fire, or are satisfactorily inerted, or, in the case of fuel tanks or lube oil tanks, or angine room or fire room bilges, have been treated in accordance with the Marine Chemist's requirements. NOT SAFE FOR HOT WORK: Means that in the compartment so designated, the requirements of Safe for Hot Work have not been met. SAFE FOR REPAIR YARD ENTRY: Means that the compartments and spaces of the flammable cryogenic liquid carrier so designated: (a) have been tested by sampling at remote sampling stations, and results indicate the atmosphere tested to be above 19.5 percent oxygen, and less than 10 percent of the lower flammable limit, or (b) are inerted CHEMIST'S ENDORSEMENT. This is to certify that I have personally determined that all spaces in the foregoing list are in accordance with NFPA 306 Control of Gas Hazards on Vessels and have found the condition of each to be in accordance with its assigned designation.

CUSTOMER COPY

Q 8 5

## HERCULES OFFSHORE CO. INVOICE NO. MARINE OPERATIONS FACILITY CUSTOMER P.O. \_ C S A M E R YES □ NO YES, COMPLETE STOCK MATERIAL TRANSFER TICKET OUTSIDE SERVICES IF YES, LIST □ YES **□**NO GAS FREEING NO CERTIFICATE REQUIRED NO 🗆 HAUL OUT FOR INSPECTION AND REPAIR YES 🛄 NO 🗆 ON WAYS ON WAYS DATE: ITEM NUMBERS 2 10 THIS SHALL SERVE AS YOUR AUTHORIZATION TO PROCEED WITH THE ABOVE. Date: . Signed: \_